

# JINAN HONGYANG CNC MACHINERY CO., LTD

## ChangSheng 800W(Φ 65\*195 Φ m/m) Woodworking

### Advertising Water-Cooled Spindle Motor

	<b>model:</b>	GDZ-65-800A
	<b>Dimensions:</b>	Φ 65*195 Φ m/m
	<b>Rotating speed:</b>	24000RPM
	<b>power:</b>	0.8KW
	<b>Voltage:</b>	220V
	<b>frequency:</b>	400HZ
	<b>Bearing:</b>	4 bearings
	<b>cooling method:</b>	Water cooling
	<b>Chuck nut:</b>	ER11A
	<b>Spindle Current:</b>	/

1. The spindle motor should be used with the inverter and the specifications and parameters of the inverter should match up with the parameters of the spindle motor. If the settings are not correct, this water-cooled spindle motor may get burned.
2. Before using, the [water cooled spindle motor](#) must ensure that the cooling circulation system can work normally, and it is strictly prohibited to use the spindle without cooling water.
3. During the storage and transportation of the spindle motor, the state of the high-speed grease inside the bearing will change. Thus, the customer should run the spindle motor at a low speed for its first use.